

Maintenance Forecast.

Forecasting by 50 Hrs / 180 Days

Aircraft Reg: EI-GTY

Current Aircraft Hours: **1592.3**

Date: 12-Dec-08

Aircraft S/N: 3808

A D Number	Service Bulletin	Detail	Frequency		Last Compliance		Next Compliance		Time Remaining	
			Hrs	Days	Hrs	Date	Hrs	Date	Hrs	Days
		50 Hour check to CAA/LAMS/H/1999	50.0	180	1592.3	10-Dec-08	1642.3	08-Jun-09	50.0	178
		100 Hour check to CAA/LAMS/H/1999	100.0		1592.3		1692.3		100.0	
		Annual check to CAA/LAMS/H/1999		365		19-May-08		19-May-09		158
		Radio Annual		365		19-May-08		19-May-09		158
E2006-0265		Transponder Calibration		365		19-May-08		19-May-09		158
86-05-02		Function check of Altimeter barometric adjustment knob		365		19-May-08		19-May-09		158
		C of A Renewal		364		17-Jun-08		16-Jun-09		186
		C of A flight test		365		19-May-08		19-May-09		158
	Lyc 480E	Drain and replenish engine oil system; Filter Inspection	50.0	124	1592.3	10-Dec-08	1642.3	13-Apr-09	50.0	122
	SL 53	10X visual inspection of Main Rotor Blade Root End	50.0		1592.3		1642.3		50.0	
	TCM 636	Operational check of ignition switch	50.0		1592.3		1642.3		50.0	
	LYC SI 1487	Oil Line Clearance Check	50.0		1592.3		1642.3		50.0	
	Lyc 366	Carburettor body screw lockwasher condition inspection	100.0		1592.3		1692.3		100.0	
		C/O Sheave Aligement	100.0		1592.3		1692.3		100.0	
		C/O engine Height Check	100.0		1592.3		1692.3		100.0	
		C/O Shaft Angle Check	100.0		1592.3		1692.3		100.0	
		Change Air Filter	100.0		1592.3		1692.3		100.0	
2007-26-12	RHC SL55 / 56	A016-4 M.R.Blade debonding of Tips (A934)	100.0		1592.3		1692.3		100.0	
	RHC SB44	Inspection of Lower Actuator Bearing Mounting Brackets	Cancelled since 2001							
2005-16-05		Inspection of Modified Door	100.0		1592.3		1692.3		100.0	

	SB89	Lubrication of upper sheave bearing	300.0	365	1398.7	21-Jun-08	1698.7	21-Jun-09	106.4	191
	RHC MM 2.502	A-181-4 Lubrication of Bearing Fitted Rev L s/n 4978	300.0	365	1493.9	18-Apr-08	1793.9	18-Apr-09	201.6	127
		Compass Check swing (Remote + Direct)		1095		19-May-08		19-May-11		888
	Lyc 301	Inspection of valve operating gear	400.0		1493.9		1893.9		301.6	
(E)2005-0023	Lyc 388C	Exhaust valve guide wear inspection	300.0		1493.9		1793.9		201.6	
	SB 643	Magneto inspection - Fitted s/n EO4IA193	500.0	1460	1493.9	03-Aug-08	1993.9	02-Aug-12	401.6	1329
		Magneto inspection - Fitted s/n EO4JA032	500.0	1460	1493.9	03-Aug-08	1993.9	02-Aug-12	401.6	1329
		Battery Capacity Check	200.0	365	1592.3	10-Dec-08	1792.3	10-Dec-09	200.0	363
88-26-01	SB-60A	Spindle inspection	500.0		1398.7	21-Jun-08	1898.7		306.4	
		Main gearbox oil change	500.0		1493.9		1993.9		401.6	
	RHC MM 2.410	Inspect Main & Tail Gearbox chip detectors	500.0	364	1302.9	19-May-08	1802.9	18-May-09	210.6	157
		36 Month Avonics Requirments (LAMS)		1095		19-May-08		19-May-11		888
	RHC SB96	Main Rotor Blade Erosion	one time		150.0	19-Apr-07				
2005-16-05	I.A.A. Ltr(190606)	Installation of Modified Door - (Tech Tool Plastics)			344.0	26/06/07				
	RHC SB97	Pedal Support Safety Tabs (a/c over 2200hrs)	N/A BY AIRCRAFT HOURS							
	RHC SB98	Removable collective spring Pin	100.0		1103.1	22-Mar-08				